

R411


APPLICATION OF STATISTICS

IN

MASS PRODUCTION

by

W. A. Shewhart
Bell Telephone Laboratories, Inc.



Outline of paper to be presented by invitation before Canton-Akron Section of the ASME in Akron, Ohio, March 20th.

Historical Background

Slide #16062 - Mass production in its
infancy.

5

Interchangeability

Slide #17802 - March of technique of
control in step with
march of ideas.

5 ✓

1. Statistical law - 1900.
2. Operation of control - 1924.
3. Operational meaning - 1928
4. Need for operationally
verifiable specifications - 1934.
5. Operationally verifiable
meanings - 1939.

WHY Should YOU Be Interested?

S3 (21624) - Tolerance range

Concept of mass production as an operation such that, if repeated again and again, it will give a result X within previously specified tolerance limits.

Problem

1. Minimize rejections.
2. Minimize cost of inspection.
3. Minimum tolerances.
 - 3.1 To save material
 - 3.2 To maximize lifting power.
4. Maximize assurance.
 - 4.1 Blowing time of fuses in shells.
 - 4.2 Drugs and hospital supplies.
 - 4.3 Strength of materials.

S4(8836) - Evidence of reduction in rejections

$$1.4 - .8 = .6.$$

S5 (18845) - Fuses - minimize tolerances.

S6 (16047) - Fuses - sequence of samples -

Maximize assurance, minimize cost of inspection.

S7 (17798) - Velocity of light: not as good state of control as S6.

Statistics in Scientific Control

S8 (23040) - Act of control (scientific)

Statistics enters each of 3 steps

Hypothesis I

S9 (8889) - State of Statistical Control

Drawings from a bowl - normal.

1. Maximum control.
2. Maximum assurance.

S10 (15437) - Control chart for averages
of numbers drawn from bowl.

S11 (21617) - Runs.

Hypothesis II

S12 (21879) - Operation of control: Steps

S13 (7809) - 204 observations: table

S14 (8837) - Control charts: 51 and 16 samples

S14 E.P. Furrell's data, table
S16 " " " " (plotted)
S15 " " " " (curves)
S16 " " " " control chart.
S17
S18 Contact resistance.

SPECIFICATION

OLD	NEW
1. Specification sets tolerance range as <u>screen</u> .	1. Specification is of the nature of an <u>hypothesis</u> .
2. Mass production based upon <u>scientific knowledge</u> .	2. Mass production is a means of <u>acquiring knowledge</u> .
3. Only tolerance range specified.	3. Tolerance range <u>plus two action limits A and B and aimed-at value C</u> <u>SI⁴(16061)</u>
4.	4. When control is attained set minimum tolerance range.
5. Inefficient overall tolerances.	5. Efficient overall tolerances.

INSPECTION

OLD

NEW

-
- | | |
|---|--|
| 1. Routine job. | 1. Important step in scientific method. |
| 2. Separate good from bad as <u>screening process</u> . | 2. <u>Detect assignable causes to be removed</u> . |
| 3. Keep eye on the <u>product</u> . | 3. Keep eye on <u>process</u> . |
| 4. Inspect <u>in accord</u> with a <u>standard</u> . | 4. Help <u>shape</u> standard in much the same way that a judge must help shape law. |
| 5. Data used primarily to screen product. | 5. Data fed back into specification to set <u>aimed-at values, etc.</u>
<u>Keep running quality report.</u> |
| 6. <u>How large a sample?</u> | 6. <u>How minimize sample size through control.</u> |
| 7. Emphasis on <u>size</u> of sample. | 7. Emphasis not only on size of sample but also on how <u>sample is obtained</u> and <u>quantity of prior information.</u> |

"Single Sampling and Double Sampling Inspection Tables", by H. F. Dodge and H. G. Romig, Bell System Technical Journal, January 1941.

CONCLUSION



sl7 (20472) - Three correlated steps.

Statistical Scientific Method + Mass Production
= New Tool of Research

W. A. SHEPPARD'S COLLECTION

